



Troubleshooting

Outside Exhaust Vents:



Please note that 30% of our winter service calls are a result of the outside **exhaust vents icing up!** Keep the area around your exterior vents free and clear of any snow and ice.

Removal of the screen (in the winter months only) will also assist in keeping vents clear.

Remember to replace the screen in the spring time.

